
OTT PLS 500
OTT PLS-C

Verdrahtung | Wiring | Raccordement | Cableado

OTT SensorLink 1000



OTT PLS 500 / PLS-C
Pressure probe cable

Color	Assignment
red	+5.5 … +28.8 V_{DC}
blue	GND
green	RS-485 A
orange	RS-485 B

OTT SensorLink 1000
SensorLink 1000 cable

Color	Assignment
blue	+5.5 … +28.8 V_{DC}
orange	GND
brown	RS-485 A
grey	RS-485 B


Note:
Ensure correct connection of the wires according to the color assignment.
Observe general safety and installation instructions.

5546000295

OTT PLS 500
OTT PLS-C

Verdrahtung | Wiring | Raccordement | Cableado

OTT SensorLink 1000



OTT PLS 500 / PLS-C
Pressure probe cable

Color	Assignment
red	+5.5 … +28.8 V_{DC}
blue	GND
green	RS-485 A
orange	RS-485 B

OTT SensorLink 1000
SensorLink 1000 cable

Color	Assignment
blue	+5.5 … +28.8 V_{DC}
orange	GND
brown	RS-485 A
grey	RS-485 B

Note:
Ensure correct connection of the wires according to the color assignment.
Observe general safety and installation instructions.

5546000295

ott.com