

OTT HydroMet GmbH | Ludwigstraße 16 | 87437 Kempten | Germany | +49 831 5617-0 | euinfo@otthydromet.com | www.otthydromet.com

Last update: July 07, 2023

Please note:

The update must be effected exclusively by OTT service or sales experts or by an authorized OTT dealer!

Get the newest release

Release Notes

V 1.22.1 (2023-07-07)

- Bugfix: in the response to the SDI-12 command "al!" Firmware version has been corrected from "CBS121" to "CBS122".

V 1.22.0 (2022-09-22)

The following enhancements/optimizations are available with this update:

- Improved behavior of the OTT CBS at internal communication errors
- Stability and performance of the device in error cases is improved